





Sliptest Australia Pty Ltd NATA Accreditation No: 15374 11 Fuchsia Way Gaven QLD 4211, Gaven, QLD, 4211 kathryn@sliptest.com.au www.sliptest.com.au 1300 754 783

OWS Tiles - 300x600mm Small Terrazzo Tiles Grey - Wet Sliptest SN080623-7

08 Jun 2023

## Slip Resistance Classification of New Pedestrian Surfaces - AS4586:2013

This Test Report Is In Accordance with Appendix A	Wet Pendulum Test
Date Tested:	08 Jun 2023
Test Report Number:	SN080623-7
Client Name & Billing Address:	OWS International Building Materials Pty Ltd - Unit1, 17 Pavesi Street, Smithfield NSW 2164
Project Name or Test Location:	Sliptest Australia NSW Headquarters - 5 Joynton Ave, Zetland NSW 2017
Surface Tested (include Texture & Underlay if Dry Carpet Test)	300x600mm Small Terrazzo Tiles / Grey
Samples and Test Information Supplied by Client	
Wet Pendulum Test carried out using :	Slider 96 (4S) Rubber slider
Testing Officer / Approved Signatory:	Shenea Neill
Pendulum in use - Calibration Date :	#1133 - Munro-Stanley Portable Skid Tester (C : 14.10.21)
Signature of Approved Signatory :	flu

Tile 1 45 Tile 2 50 Tile 3 47 Tile 4 50 Tile 5 47	0 7 0	43 47 46 47	42 45 44	41 44 43	41	41	N/A N/A	
Tile 3 47 Tile 4 50	7	46	44			44	N/A	
Tile 4 50	0			43			1,	
		47	40	1	43	43	N/A	
Tile 5 47	7		46	45	45	45	N/A	
		45	43	43	42	43	N/A	Christian

CLASSIFICATION using Slider 96 (4S Slider) P3 = 35 - 44

OWS Tiles - 300x600mm Small Terrazzo Tiles Grey - Wet Sliptest SN080623-7

**CONFIDENTIAL** 

Page 1

Version:

Accredited for Compliance with ISO/IEC 17025. The information presented herein and on the Sliptest Report is copyright and is protected by copyright law, any reproduction of this information and test report except in full is prohibited. Sliptest Australia Pty. Ltd. performed this on site test with reference to the following Australian Standard testing criteria, of AS 4586:2013 Classification of new pedestrian surface materials. Appendix A - Wet Pendulum Test Method and Hand Book HB 198: 2014 with reference to AS/NZS 4663: 2004 Slip Resistance measurement of existing pedestrian surfaces and HB 197: 1999. These results to not account for Future Wear, Maintenance or Contamination of this surface once in-situ.

Page 1 of 1 - END OF REPORT